Tree Inventory and Preservation Plan Report 12506 and 12698 Heart Lake Road Caledon, Ontario

prepared for

TOWN OF CALEDON PLANNING RECEIVED

October 17th, 2025

byPATH: Landscape Architecture Inc.

prepared by



PO Box 1267 Lakeshore W PO 146 Lakeshore Road West Oakville ON L6K 0B3 289.837.1871 www.kuntzforestry.ca consult@kuntzforestry.ca

14 October 2025

KUNTZ FORESTRY CONSULTING Inc. Project P4768

Introduction

Kuntz Forestry Consulting Inc. was retained by byPATH Landscape Architecture Inc. to complete a Tree Inventory and Preservation Plan Report in support of a development application for properties at 12506 and 12698 Heart Lake Road in the Town of Caledon, Ontario. The subject properties are located on the west side of Heart Lake Road, south of Old School Road, within a rural area. The western portion of 12698 Heart Lake Road is protected as the Greenbelt and regulated by the Toronto and Region Conservation Authority (TRCA).

The work plan for this study included the following:

- Prepare inventory of the tree resources over 10cm on and within six metres of the proposed development;
- Evaluate tree saving opportunities based on proposed site plans and grading; and,
- Document the findings in a Tree Inventory and Preservation Plan report.

Trees included were visually assessed for condition utilizing the following parameters:

Tree # - number assigned to trees that corresponds to Figures 1-7.

Species - common and botanical names provided in the inventory table.

DBH - diameter (centimeters) at breast height, measured at 1.4 m above the ground.

Condition - condition of tree considering trunk integrity (TI), crown structure (CS) and crown vigor (CV). Condition ratings include poor (P), fair (F), and good (G).

Crown Die Back – Percentage of dead branches within the crown.

Drip Line - Crown radius: and

Comments – Any other relevant tree condition information.

The results of the evaluation are provided below.

Methodology

Trees measuring over 10cm DBH on and within six metres of the proposed development were identified included in the tree inventory. Trees were located using a handheld GPS unit (Trimble GeoExplorer® 6000 series) accurate to ±1m and a topographic survey provided for the subject properties. Trees on the subject properties were tagged with numbers 501-600, 351-460. Trees located on the adjacent properties are identified with letters A-I. Hedgerows and rows of trees were inventoried as polgons and identified as P1-P3. Tree locations are shown on Figures 1-7. See Table 1 for the results of the inventory.

Existing Site Conditions

The subject properties are currently occupied by residential dwellings and amenities, farming facilities, driveways, and agricultural land. Tree resources exist in the form of landscape trees and natural generations. Refer to Figures 1-7 for the existing site conditions.

Individual Tree Resources

The tree inventory was conducted on 27 August 2025 and 9 October 2025. The inventory documented 219 individual trees and three tree polygons on and within six metres of the proposed

development. Refer to Table 1 for the full tree inventory and Figures 1-7 for the location of tree reported in the tree inventory.

Tree resources included in the inventory are White Fir (Abies concolor), Freeman Maple (Acer x freemanii), Amur Maple (Acer ginnala), Norway Maple (Acer platanoides), Crimson King Maple (Acer platanoides 'Crimson King'), Silver Maple (Acer saccharinum), Sugar Maple (Acer saccharinum), White Birch (Betula papyrifera), Northern Catalpa (Catalpa speciosa), False Cypress (Chamaecyparis spp.), European Beech (Fagus sylvatica), Copper Beech (Fagus sylvatica f. Purpurea), Columnar Weeping Copper Beech (Fagus sylvatica 'Purple Fountain'), Ginkgo (Ginkgo biloba), Shademaster Honey Locust (Gleditsia triacanthos 'inermis'), Black Walnut (Juglans nigra), Tamarack (Larix laricina), Apple (Malus spp.), Norway Spruce (Picea abies), White Spruce (Picea glauca), Blue Spruce (Picea pungens), Austrian Pine (Pinus nigra), Schubert Cherry (Prunus virginiana 'Schubert'), Red Oak (Quercus rubra), Corkscrew Willow (Salix matsudana), Willow (Salix spp.), Ivory Silk Lilac (Syringa reticulata 'Ivory Silk'), Eastern White Cedar (Thuja occidentalis), and White Elm (Ulmus americana).

Proposed Development

The proposed development includes the demolition of the existing buildings and the construction of four commercial buildings and surface parking. The construction of a new stormwater management pond is proposed on the north side of the subject property. The ravine ecosystem and a plantation forest on the north side of the subject properties will be retained. Refer to Figures 1-7 for the proposed development.

Discussion

The following sections provide a discussion and analysis of development impacts, tree removal requirements and tree preservation relative to the proposed development.

Development Impacts/Tree Removals

The removal of 143 individual trees and one tree polygon is required to accommodate the proposed development. Required tree removals include Trees 351-374, 387-393, 429-436, 443-458, 501-577, 586-600, and P1. All trees that require removal are located on the subject properties.

The removal of Trees 394, 397, 398, and 400 is recommended due to their poor and/or hazardous condition. Refer to Figures 1-7 for the location of the proposed tree removals.

- All tree removals must be conducted outside of the bird breeding season (April 1st August 1st).
- The owner must retain the same Certified Arborist to carry out the recommendations in TIPP report to the satisfaction of the Town. A certification letter will be provided by a Certified Arborist that tree removals have been completed as per the approved TIPP report. An additional certification letter from the same Arborist will be provided that confirms any long-term requirements and recommendations in the report have been carried out.
- The owner is solely responsible for ongoing maintenance and repairs to tree protection fencing throughout the proposed development.

Tree Preservation

The preservation of the remaining 72 individual trees and two tree polygons will be possible with appropriate tree protection measures. Recommended tree preservation includes Trees, 375-386, 390-393, 395, 396, 399, 401-428, 437-442, 459, 460, 578-585, A-I, P2, and P3. Sediment and erosion control fencing should be sufficient as tree protection fencing. Refer to Figures 1-7 for the location of prescribed tree preservation fencing, further tree preservation plan notes and the tree protection fencing detail.

- Areas within the tree protection zone shall remain undisturbed for the duration of site construction and shall not be used for the storage of excavated fill, building/construction materials, or equipment.
- The limit of tree protection hoarding shall be confirmed in the field by the consulting arborist, Town staff, and conservation authority (if applicable). The Owner/Applicant shall be responsible for ongoing maintenance and repairs to the tree protection fencing to the satisfaction of the Town, until final approval by the Town and conservation authority (if applicable). The Owner/Applicant shall not remove and not cause or permit any tree preservation fencing to be removed without the approval of the Town and conservation authority (if applicable).

Tree Compensation

The Town of Caledon requires tree compensation for any healthy tree removal. The compensation ratio is below:

Diameter at Breast Height (DBH)	Compensation Ratio
<10cm	Not applicable
10-20cm	1:1
21-35cm	2:1
36-50cm	3:1
51-65cm	4:1
>65cm	5:1

The removal of 143 individually inventoried trees and 34 trees in Tree P1 is proposed to accommodate the proposed site plan; However, several trees are not applicable to compensation requirements. Trees 394, 397, 398, 400, 501, 507, 508, 511, 512, 518, 522, 526, 535, 542, 549, 574, 575, 577, 591, 594, and five trees within Tree P1 have poor and/or hazardous conditions.

As such, a total of 357 replacement plantings is required on the subject property. Refer Tables 1 and 2 for replacement trees required per tree removal.

Summary and Recommendations

Kuntz Forestry Consulting Inc. was retained by byPATH: Landscape Architecture Inc.. to complete a Tree Inventory and Preservation Plan in support of a development application for the propertyies located at 12506 and 12698 Heart Lake Road in Caledon, Ontario. A tree inventory was conducted and reviewed in the context of the proposed development plan.

The findings of the study indicate a total of 219 trees and three tree polygons on and within six metres of the proposed development. The removal of 143 trees and one tree polygon is required to accommodate the proposed development. The removal of additional four trees is

recommended due to poor and/or hazardous conditions. The preservation of the remaining 52 trees and two tree polygons will be possible with appropriate tree protection measures.

The following recommendations are suggested to minimize impacts to trees identified for preservation. Refer to Figures 1-7 for additional Tree Protection Plan Notes and tree preservation fence detail.

- Tree protection barriers and fencing should be erected at locations as prescribed on Figures 1-7. All tree protection measures should follow the guidelines as set out in the tree preservation plan notes and the tree preservation fencing detail.
- No construction activity including surface treatments, excavations of any kind, storage of
 materials or vehicles, unless specifically outlined above, is permitted within the area identified
 on Figures 1-7 as a tree protection zone (TPZ) at any time during or after construction.
- Site visits, pre, during and post construction is recommended by either a certified consulting arborist (I.S.A.) or registered professional forester (R.P.F.) to ensure proper utilization of tree protection barriers. Trees should also be inspected for damage incurred during construction to ensure appropriate pruning or other measures are implemented.

Town of Caledon Tree Protection Notes

- During construction and prior to final approval by the Town, the consulting Arborist along with appropriate Town staff shall intermittently inspect the entire site. Any noted hazardous trees must be identified and removed prior to Assumption or earlier if deemed hazardous at the sole cost of the Owner/Applicant. Any records of maintenance or removals are to be submitted to the Town.
- Compensation will be required for all tree removals at a rate as determined by the Town's
 Tableland Tree Removal Compensation. Tree compensation planting will be in addition to the
 standard required planting. In the event tree compensation cannot be accommodated for in
 the planting design, financial compensation shall be collected at a rate (per tree) as determined
 by the Town. Based on the compensation ratio, 207 replacement trees are required to
 compensate for the removal of trees on the subject property.
- Removals should occur outside of the breeding bird season (April 1- August 1). If this is not
 possible, clearance with an ecologist should occur prior to construction to ensure no loss of
 bird nest, egg or unfledged young.
- Any trees located on the property line or on the adjacent property that are proposed to be removed, pruned or injured, will require written consent from the adjacent landowner. All correspondence is to be forwarded to the Town prior to any removals.
- Minor grading works may be permitted at the edge of the preservation zone as required to correct localized grading issues adjacent to the proposed development at the discretion of the Town. This work is to be undertaken under the supervision of the consulting Arborist. The consulting Arborist is to verify in writing to the Town, confirming that the work has been completed as per the approved design using best arboricultural practices.

- Areas within the tree protection zone shall remain undisturbed for the duration of site construction and shall not be used for the storage of excavated fill, building/construction material, structures or equipment.
- The limit of tree protection hoarding shall be confirmed in the field by the consulting arborist, Town staff and conservation authority (if applicable). The Owner/Applicant shall be responsible for ongoing maintenance and repairs to tree protection fencing to the satisfaction of the Town, until final approval by the Town and conservation authority (if applicable). The Owner/Applicant shall not remove and not cause or permit any tree preservation fencing to be removed without the approval of the Town and conservation authority (if applicable).

Respectfully Submitted, Kuntz Forestry Consulting Inc.

Kaho Hayashi

Kaho Hayashi, B.Sc., M.Sc.F. Senior Forest Ecologist ISA Certified Arborist #ON-2153A Tree Risk Assessment Qualified Tel: 289-837-1871 ext. 103

Cell: 289-835-3298

Email: kaho.hayashi@kuntzforestry.ca

<u>Limitations of Assessment</u>

Only the tree(s) identified in this report were included in the inventory. The assessment of the trees presented in this report has been made using accepted arboricultural techniques. These may include a visual examination taken from the ground of all the above-ground parts of the tree for structural defects, scars, external indications of decay such as fungal fruiting bodies, evidence of attack by insects, discoloured foliage, the condition of any visible root structures, the degree of lean (if any), the general condition of the trees and the identification of potentially hazardous trees or recommendations for removal (if applicable). Where trees could not be directly accessed (ie. due to obstructions, and/or on neighbouring properties), trees were assessed as accurately as possible from nearby vantage points.

Locations of trees provided in the report are determined as accurately as possible based on the best information available. If official survey information is not provided, tree location in the report may not be exact. In this case, if trees occur on or near property boundaries, an official site survey may be required to determine ownership utilizing specialized survey protocol to gain precise location.

Furthermore, recommendations made in this report are based on the site plans that have been provided at the time of reporting. These recommendations may no longer be applicable should changes be made to the site plan and/or grading, servicing, or landscaping plans following report submission.

Notwithstanding the recommendations and conclusions made in this report, it must be recognized that trees are living organisms, and their health and vigor constantly change over time. They are not immune to changes in site conditions or seasonal variations in the weather conditions. Any tree will fail if the forces applied to the tree exceed the strength of the tree or its parts.

Although every effort has been made to ensure that this assessment is reasonably accurate, the trees should be re-assessed periodically. The assessment presented in this report is valid at the time of inspection.

Table 1. Tree Inventory

Location: 12506-12698 Heart Lake Road, Caledon Date: 27 August & 9 October 2025 Surveyors: KH

Tree #	Common Name	Scientific Name	DBH	TI	cs	CV	CDB	DL	Comments	Owner	Action	Comp.
351	Blue Spruce	Picea pungens	17	G	G	F-G		1.5		Private	Remove	1
352	Blue Spruce	Picea pungens	18	G	G	G		1.5		Private	Remove	1
353	Blue Spruce	Picea pungens	18	G	G	G		1		Private	Remove	1
354	Blue Spruce	Picea pungens	17	G	G	G		1.5		Private	Remove	1
355	Crimson King Maple	Acer platanoides 'Crimson King'	18	G	G	F		1.5	Chlorosis (H)	Private	Remove	1
356	Crimson King Maple	Acer platanoides 'Crimson King'	12.5	G	G	F		1.5	Chlorosis (H)	Private	Remove	1
357	Crimson King Maple	Acer platanoides 'Crimson King'	12	G	G	F		1	Chlorosis (H)	Private	Remove	1
358	Crimson King Maple	Acer platanoides 'Crimson King'	17.5	F	G	F		1.5	Chlorosis (H), seam (M)	Private	Remove	1
359	Norway Maple	Acer platanoides	51.5	F-G	G	G		5	Stem wounds (L) at base	Private	Remove	4
360	Norway Maple	Acer platanoides	38	F	G	F-G		4	Co-dominance at 1.8m, growth deficit (L)	Private	Remove	3
361	Norway Maple	Acer platanoides	54.5	F-G	G	F-G		5	Co-dominance at 1.9m	Private	Remove	4
362	Norway Maple	Acer platanoides	55.5	F	G	F-G		5	Co-dominance at 1.5m with included bark (M)	Private	Remove	4
363	Norway Maple	Acer platanoides	44	F-G	G	F-G		4	Co-dominance at 1.8m	Private	Remove	3
364	Norway Maple	Acer platanoides	46	F	G	F-G	10	4	Growth deficit (L), lean (L), co- dominance at 1.8m with 3 stems	Private	Remove	3
365	Norway Maple	Acer platanoides	53.5	F-G	G	F	15	4	Co-dominance at 1.8m with included bark (M), sweep (L)	Private	Remove	4
366	Sugar Maple	Acer saccharum	51.5	G	G	G		5		Private	Remove	4
367	Norway Maple	Acer platanoides	42.5	F-G	G	F-G		4	Co-dominance at 1.9m with included bark (L)	Private	Remove	3
368	Norway Maple	Acer platanoides	52.5	F-G	G	F		5	Co-dominance at 1.5m and 2m with 3 stems, chlorosis (M)	Private	Remove	4
369	Norway Maple	Acer platanoides	39	F-G	G	F		4	Union at 2m, crook (L), bow (L), chlorosis (M)	Private	Remove	3
370	Norway Maple	Acer platanoides	43	F-G	G	F		4	Union at 1.8m, chlorosis (M)	Private	Remove	3
371	Norway Maple	Acer platanoides	46	F-G	G	F		4	Union at 1.8m, chlorosis (M)	Private	Remove	3
372	Sugar Maple	Acer saccharum	35	G	G	G		4		Private	Remove	2

Tree #	Common Name	Scientific Name	DBH	TI	CS	CV	CDB	DL	Comments	Owner	Action	Comp.
373	Norway Maple	Acer platanoides	42.5	F	G	F		5	Union at 1.6m with 4 stems, chlorosis (M)	Private	Remove	3
374	Sugar Maple	Acer saccharum	43	G	G	G		5		Private	Remove	3
375	Norway Maple	Acer platanoides	27.5	F-G	G	F		4	Sweep (L), co-dominance at 1.9m	Town	Preserve	
376	Silver Maple	Acer saccharinum	46, 33, 27, 19	F-G	G	F-G		5	Union at base, stem wounds (L)	Town	Preserve	
377	Norway Maple	Acer platanoides	12	G	G	F		1	Chlorosis (H)	Town	Preserve	
378	Norway Maple	Acer platanoides	14	F	G	F		1	Seam (L), frost crack (L), chlorosis (H)	Private	Preserve	
379	Blue Spruce	Picea pungens	20	G	G	G		1.5		Private	Preserve	
380	Blue Spruce	Picea pungens	26	G	G	G		3		Private	Preserve	
381	Blue Spruce	Picea pungens	~28	G	G	G		3		Private	Preserve	
382	White Elm	Ulmus americana	39	F-G	G	F-G		4	Co-dominance at 3m with included bark (L)	Private	Preserve	
383	Blue Spruce	Picea pungens	~38	G	G	G		3		Private	Preserve	
384	Blue Spruce	Picea pungens	~32	G	G	F		2	Sparse crown (M)	Private	Preserve	
385	Blue Spruce	Picea pungens	~32	G	G	F-G		2		Private	Preserve	
386	Black Walnut	Juglans nigra	23	G	G	G		3		Private	Preserve	
387	Norway Maple	Acer platanoides	84	F	F	F-G	20	5	Union at 2m, bow (VL), crook (M), broken branches (M)	Private	Remove	5
388	Norway Maple	Acer platanoides	76	F	F	F-G	10	5	Lean (L), union at 2m	Private	Remove	5
389	Blue Spruce	Picea pungens	17	G	G	G		1.5		Private	Remove	1
390	Blue Spruce	Picea pungens	18	G	G	G		2		Private	Preserve	
391	Blue Spruce	Picea pungens	21	G	G	G		2		Private	Preserve	
392	Blue Spruce	Picea pungens	20	G	G	G		1.5		Private	Preserve	
393	Blue Spruce	Picea pungens	23	G	G	G		2		Private	Preserve	
394	Norway Maple	Acer platanoides	100	Р	F	F	25	6	Union at base but 1 stem cut with rot, seam (M), co-dominance at 2m with split, bow (L), lost leaders	Private	Remove (condition)	0
395	Norway Maple	Acer platanoides	32, 28.5	F-G	F-G	F-G		3	Co-dominance at 0.3m with included bark (L), sweep (L), tar spots (L)	Private	Preserve	
396	Norway Maple	Acer platanoides	19.5	F-G	F-G	F-G		2	Lean (L)	Private	Preserve	
397	Norway Maple	Acer platanoides	63.5	Р	P-F	F-G	15	5	Co-dominance at 3m, multiple cankers	Private	Remove (condition)	0
398	Norway Maple	Acer platanoides	65	Р	F-G	F-G		6	Cavity at 0.6m, union at 1.6m, tar spots (L)	Private	Remove (condition)	0
399	Norway Maple	Acer platanoides	42.5	F-G	G	G		5	Sweep (L	Private	Preserve	

Tree #	Common Name	Scientific Name	DBH	TI	cs	CV	CDB	DL	Comments	Owner	Action	Comp.
400	Norway Maple	Acer platanoides	57.5	Р	G	F-G		4	Hazard, cavity (H) on lower stem	Private	Remove (condition)	0
401	Norway Maple	Acer platanoides	44.5	F-G	G	F-G		4	Crook (L), sweep (L)	Private	Preserve	
402	Norway Maple	Acer platanoides	41	F	F-G	F-G		4	Co-dominance at 4m, crook (M), stem wounds (L)	Private	Preserve	
403	Norway Maple	Acer platanoides	21	P-F	G	F		2	Bow (M), canker (M), poor form, crook (M), epicormic branches (M)	Private	Preserve	
404	Norway Maple	Acer platanoides	19.5	F	G	F		2	Seam (M), lean (L), poor form, crook (M), epicormic branches (M)	Private	Preserve	
405	Norway Maple	Acer platanoides	37	F-G	G	F-G		4	Lean (L), co-dominance in crown	Private	Preserve	
406	Norway Maple	Acer platanoides	76	F-G	G	F	15	6	Co-dominance at 2.5m, tar spots (M)	Private	Preserve	
407	Norway Maple	Acer platanoides	37.5	F-G	G	F-G		4	Lean (L)	Private	Preserve	
408	Norway Maple	Acer platanoides	32.5	F-G	G	F-G		4	Lean (L)	Private	Preserve	
409	Norway Maple	Acer platanoides	48, 33.5	Р	G	F-G		5	Union at 1m, larger stem has canker (H)	Private	Preserve	
410	Norway Maple	Acer platanoides	45	F-G	G	F-G		5	Sweep (L), crook (L)	Private	Preserve	
411	Norway Maple	Acer platanoides	44.5, 32.5	Р	F-G	F	20	5	Union at base, canker (M) on larger stem with crack, seam (M)	Private	Preserve	
412	Norway Maple	Acer platanoides	71	F	F-G	F-G		6	Union at 1.7m, bow (L), crook (M), sweep (M)	Private	Preserve	
413	Norway Maple	Acer platanoides	41	F-G	G	F-G		4	Sweep (L), crook (L), lean (L)	Private	Preserve	
414	Norway Maple	Acer platanoides	22.5	F-G	F-G	F-G		3	Bow (L), crook (M), asymmetrical crown (M)	Private	Preserve	
415	Norway Spruce	Picea abies	83	G	G	F-G		4		Private	Preserve	
416	Norway Spruce	Picea abies	83	F-G	G	F-G		4	Lean (L)	Private	Preserve	
417	Norway Spruce	Picea abies	63.5	F-G	G	F	15	4	Dead branches (L)	Private	Preserve	
418	Norway Spruce	Picea abies	66.5	G	G	F-G		4		Private	Preserve	
419	Norway Spruce	Picea abies	50	G	G	F-G		3		Private	Preserve	
420	Norway Spruce	Picea abies	83.5	G	G	F-G		4		Private	Preserve	
421	Norway Maple	Acer platanoides	67.5	F-G	G	F-G		7	Lean (L), union at 2m with 5 stems	Private	Preserve	
422	Norway Maple	Acer platanoides	62.5	F-G	G	F-G		6	Lean (L)	Private	Preserve	
423	Norway Spruce	Picea abies	72	G	G	F-G		4		Private	Preserve	
424	Norway Spruce	Picea abies	61	F-G	G	F-G		4	Union at 2m	Private	Preserve	
425	Norway Spruce	Picea abies	65.5	G	G	F-G		4		Private	Preserve	
426	Norway Spruce	Picea abies	82	F-G	G	F-G		4	Co-dominance at 4m	Private	Preserve	
427	Blue Spruce	Picea pungens	42	G	G	F-G		2		Private	Preserve	

Tree #	Common Name	Scientific Name	DBH	TI	cs	CV	CDB	DL	Comments	Owner	Action	Comp.
428	Blue Spruce	Picea pungens	46	G	G	F		3	Sparse crown (M)	Private	Preserve	
429	Blue Spruce	Picea pungens	35	G	G	G		3		Private	Remove	3
430	Blue Spruce	Picea pungens	36	G	G	G		3		Private	Remove	3
431	Blue Spruce	Picea pungens	35	G	G	G		3		Private	Remove	3
432	Blue Spruce	Picea pungens	33	G	G	F		3	Lean (L), sparse crown (M)	Private	Remove	2
433	Blue Spruce	Picea pungens	33	G	G	G		3		Private	Remove	2
434	Blue Spruce	Picea pungens	32	G	G	G		3		Private	Remove	2
435	Blue Spruce	Picea pungens	33	G	G	G		3		Private	Remove	2
436	Sugar Maple	Acer saccharum	53	F-G	G	G		5	Co-dominance at 2m with 9 stems	Private	Remove	4
437	Blue Spruce	Picea pungens	18	G	G	G		1		Private	Preserve	
438	Blue Spruce	Picea pungens	18	G	G	G		1		Private	Preserve	
439	White Spruce	Picea glauca	11	G	G	G		1.5		Private	Preserve	
440	Blue Spruce	Picea pungens	18	G	G	G		1.5		Private	Preserve	
441	Blue Spruce	Picea pungens	16	G	G	G		1.5		Private	Preserve	
442	Blue Spruce	Picea pungens	22	G	G	G		1.5		Private	Preserve	
443	Blue Spruce	Picea pungens	20	G	G	G		1.5		Private	Remove	1
444	Blue Spruce	Picea pungens	16	G	G	G		1		Private	Remove	1
445	Norway Maple	Acer platanoides	49.5, 48	F	G	F	20	5	Union at 1m and 1.6m with 5 stems, dead branches (L)	Private	Remove	3
446	Norway Maple	Acer platanoides	50.5	F-G	G	F-G		5	Co-dominance at 1.8m, union at 1.6m	Private	Remove	3
447	Silver Maple	Acer saccharinum	69.5	F-G	G	F-G		7	Union at 2m, epicormic branches (M)	Private	Remove	5
448	Silver Maple	Acer saccharinum	47	F-G	G	F	25	5	Union at 1.6m, broken branches (L), dead branches (L)	Private	Remove	3
449	Silver Maple	Acer saccharinum	55	F-G	G	F-G	10	5	Union at 1.5m with 7 stems	Private	Remove	4
450	Silver Maple	Acer saccharinum	44, 32, 24	F	G	F	20	6	Union at 1m, dead branches (L)	Private	Remove	3
451	Silver Maple	Acer saccharinum	51	F-G	G	F	20	5	Co-dominance at 2m with 3 stems, dead branches (L)	Private	Remove	4
452	Norway Maple	Acer platanoides	31	G	G	F-G		4	Tar spots (L)	Private	Remove	2
453	Norway Maple	Acer platanoides	31, 28	F-G	G	F-G		4	Co-dominance at 0.5m, girdling roots, tar spots (L)	Private	Remove	2
454	Norway Maple	Acer platanoides	45.5	F-G	G	F-G		5	Co-dominance at 2m, tar spots (L)	Private	Remove	3
455	Norway Maple	Acer platanoides	41.5	G	G	F-G		4	Tar spots (L)	Private	Remove	3
456	Crimson King Maple	Acer platanoides 'Crimson King'	17	G	G	F		2		Private	Remove	1

Tree #	Common Name	Scientific Name	DBH	TI	cs	CV	CDB	DL	Comments	Owner	Action	Comp.
457	Black Walnut	Juglans nigra	36	F-G	G	G		4	Co-dominance at 2m with included bark (M)	Private	Remove	3
458	Black Walnut	Juglans nigra	38	F-G	G	G		4	Co-dominance at 4m	Private	Remove	3
459	Norway Maple	Acer platanoides	54, 46	F	G	F-G		5	Union at 1.2m, rot on broken branches (M)	Private	Preserve	
460	Norway Maple	Acer platanoides	50	F-G	G	F-G	15	5	Broken branches (L), tar spots (L), union at 1.8m with 6 stems	Private	Preserve	
501	White Fir	Abies concolor	~22	G	G	Р	40	1.5	Dead leader, dead branches (M)	Private	Remove	0
502	Norway Maple	Acer platanoides	26	G	G	F-G		3	Tar spots (L)	Private	Remove	2
503	Norway Maple	Acer platanoides	33	G	G	F-G		3	Tar spots (L)	Private	Remove	2
504	Crimson King Maple	Acer platanoides 'Crimson King'	15	G	G	G		2	Tar spots (L)	Private	Remove	1
505	Norway Maple	Acer platanoides	35	G	G	F-G		3	Tar spots (L)	Private	Remove	2
506	Norway Maple	Acer platanoides	34	G	G	F-G		3	Tar spots (L)	Private	Remove	2
507	Norway Maple	Acer platanoides	21	P-F	G	F-G		2	Stem wound (M)at base with rot, tar spots (L)	Private	Remove	0
508	Silver Maple	Acer saccharinum	34.5, 24.5	F-G	F	P-F	30	4	Union at 1m with included bark (L), epicormic branches (H), dead branches (M)	Private	Remove	0
509	Norway Maple	Acer platanoides	18	G	G	G		3	Tar spots (L)	Private	Remove	1
510	Norway Maple	Acer platanoides	17	G	G	G		2	Tar spots (L)	Private	Remove	1
511	Norway Maple	Acer platanoides	34	Р	Р	Р	90	1	Almost dead, only one lower branches alive, missing bark, hazard	Private	Remove	0
512	Norway Maple	Acer platanoides	16	P-F	G	F-G		2	Lean (L), frost crack (H) with rot, epicormic branches (M)	Private	Remove	0
513	Silver Maple	Acer saccharinum	44.5, 30	F	G	F-G		5	Co-dominance at 0.6m with included bark (L), epicormic branches (M)	Private	Remove	3
514	Silver Maple	Acer saccharinum	76.5	F-G	G	F-G		5	Co-dominance at 3m, epicormic branches (M)	Private	Remove	5
515	Honey Locust (shademaster)	Gleditsia triacanthos 'inermis'	26	G	G	F	15	4	Lean (VL)	Private	Remove	2
516	Crimson King Maple	Acer platanoides 'Crimson King'	26.5	G	G	F-G		2		Private	Remove	2
517	Ivory Silk Lilac	Syringa reticulata 'Ivory Silk'	22.5	G	G	G		2		Private	Remove	2
518	Norway Maple	Acer platanoides	56.5	P-F	G	F-G		4	Cavity at 1.6m, tar spots (L)	Private	Remove	0

Tree #	Common Name	Scientific Name	DBH	TI	cs	CV	CDB	DL	Comments	Owner	Action	Comp.
519	White Birch	Betula papyrifera	28.5, 24, 13.5	F-G	G	F-G		4	Union at base, lean (L)	Private	Remove	2
520	Amur Maple	Acer ginnala	14, 12, <10	G	G	G		2	Union at base with 5 stems	Private	Remove	1
521	Amur Maple	Acer ginnala	14.5, <10	G	G	G		2	Union at 0.3m with 7 stems	Private	Remove	1
522	Apple	Malus spp.	11.5	G	G	P-F	30	2	Sparse crown (H), dead bran	Private	Remove	0
523	Amur Maple	Acer ginnala	15, 13, 13, 13	G	G	F-G		3	Union at base, epicormic branches (M)	Private	Remove	1
524	Blue Spruce	Picea pungens	34	G	G	G		2		Private	Remove	2
525	Blue Spruce	Picea pungens	29	F-G	G	F		1	Sweep (L)	Private	Remove	2
526	Blue Spruce	Picea pungens	33	G	G	P-F	20	2	Sparse crown (M), in decline	Private	Remove	0
527	Blue Spruce	Picea pungens	25	G	G	F		1.5	Epicormic branches (L), sweep (L)	Private	Remove	2
528	Silver Maple	Acer saccharinum	55, 48	F-G	G	F-G	10	6	Co-dominance at 1m with included bark (M), epicormic branches (M)	Private	Remove	4
529	Silver Maple	Acer saccharinum	80.5	F-G	G	F-G		6	Co-dominance at 1.8m, epicormic branches (M)	Private	Remove	5
530	Silver Maple	Acer saccharinum	50, 38, 30	F-G	G	F-G	5	6	Union at 1m	Private	Remove	3
531	Columnar Weeping Copper Beech	Fagus sylvatica 'Purple Fountain'	13	G	G	G		1		Private	Remove	1
532	False Cypress	Chamaecyparis spp.	11	G	G	G		1		Private	Remove	1
533	Ginkgo	Ginkgo biloba	15.5	F-G	G	F-G		1.5	Co-dominance at 1.8m	Private	Remove	1
534	Red Oak	Quercus rubra	15	G	G	G		2		Private	Remove	1
535	Corkscrew Willow	Salix matsudana	18, 16, 16, 13, <10	G	G	P-F	40	2	Union at base with 7 stems	Private	Remove	0
536	Norway Maple	Acer platanoides	30	G	G	G		4	Tar spots (L)	Private	Remove	2
537	Norway Maple	Acer platanoides	34	G	G	G		3	Tar spots (L)	Private	Remove	2
538	Norway Maple	Acer platanoides	39	G	G	G		3	Tar spots (L)	Private	Remove	3
539	European Beech	Fagus sylvatica	14, 13, 10	G	G	G		2	Union at 0.3m	Private	Remove	1
540	Austrian Pine	Pinus nigra	54	G	G	F-G		4	Diplodia (L)	Private	Remove	4
541	Austrian Pine	Pinus nigra	47	F-G	G	F-G		3	Lean (L), sweep (L), union at 2m	Private	Remove	3
542	Austrian Pine	Pinus nigra	32, 26	P-F	G	F-G		4	Union at base, larger stem lean (H) then grow upward, poor form, sweep (L)	Private	Remove	0
543	Austrian Pine	Pinus nigra	39	G	G	F-G		3	Lean (L)	Private	Remove	3
544	Austrian Pine	Pinus nigra	56	G	G	F-G		4	Sweep (L)	Private	Remove	4
545	Norway Spruce	Picea abies	64.5	G	G	F-G		4		Private	Remove	4
546	Norway Spruce	Picea abies	47.5	G	G	F-G		3		Private	Remove	3

Tree #	Common Name	Scientific Name	DBH	TI	cs	CV	CDB	DL	Comments	Owner	Action	Comp.
547	Norway Spruce	Picea abies	53.5	G	G	F	20	3		Private	Remove	4
548	Norway Spruce	Picea abies	49	F	G	F		3	Exposed roots (M)with wounds, fruiting bodies at base, growth deficit (L)	Private	Remove	3
549	Norway Spruce	Picea abies	47.5	G	G	P-F	30	3	Exposed roots (M)with wounds, fruiting bodies near base, in decline	Private	Remove	0
550	Austrian Pine	Pinus nigra	47.5	G	G	G		3	Sweep (L)	Private	Remove	3
551	Austrian Pine	Pinus nigra	31	G	F	G		2	Asymmetrical crown (H)	Private	Remove	2
552	Silver Maple	Acer saccharinum	27, 18	F-G	G	G		3	Union at 0.8. with included bark (M)	Private	Remove	2
553	White Birch	Betula papyrifera	13, 10, 8	G	G	G		2	Union at base	Private	Remove	1
554	White Birch	Betula papyrifera	12, 10.5, 8	G	G	G		2	Union at base	Private	Remove	1
555	White Birch	Betula papyrifera	17.5, 9.5	G	G	G		2	Union at base, sweep (L)	Private	Remove	1
556	White Birch	Betula papyrifera	13, 10, 8	G	G	G		2	Union at base	Private	Remove	1
557	White Birch	Betula papyrifera	12, 10.5, 10	G	G	G		2	Union at base	Private	Remove	1
558	Eastern White Cedar	Thuja occidentalis	20, 19	F-G	G	F-G		2	Union at 0.2m	Private	Remove	1
559	Tamarack	Larix laricina	19	G	G	G		2		Private	Remove	1
560	White Spruce	Picea glauca	22	G	G	G		2		Private	Remove	2
561	White Spruce	Picea glauca	22	G	G	G		2		Private	Remove	2
562	Austrian Pine	Pinus nigra	48	F-G	G	F-G		3	Lean (L), sweep (L)	Private	Remove	3
563	Austrian Pine	Pinus nigra	50	F-G	G	F-G		3	Co-dominance at 4m with 3 stems, sweep (L)	Private	Remove	3
564	Austrian Pine	Pinus nigra	49	G	G	F-G		4		Private	Remove	3
565	Silver Maple	Acer saccharinum	29.5	F-G	G	G		3	Co-dominance in crown	Private	Remove	2
566	White Spruce	Picea glauca	18	G	G	G		2		Private	Remove	1
567	White Spruce	Picea glauca	21	G	G	G		2		Private	Remove	2
568	White Spruce	Picea glauca	19	G	G	G		2		Private	Remove	1
569	Austrian Pine	Pinus nigra	42	F-G	G	F-G		3	Sweep (L), crook (L)	Private	Remove	3
570	Austrian Pine	Pinus nigra	50	F	G	F-G		3	Union at 1.5m with 3 stems	Private	Remove	3
571	Sugar Maple	Acer saccharum	20	G	G	F-G		2	Tar spots (L)	Private	Remove	1
572	Sugar Maple	Acer saccharum	17	G	G	F-G	20	2	Tar spots (L)	Private	Remove	1
573	Sugar Maple	Acer saccharum	18.5	G	G	G		2	Tar spots (L)	Private	Remove	1
574	Schubert Cherry	Prunus virginiana 'Schubert'	17	G	G	P-F	25	2	Sap oozing, dead branches (M)	Private	Remove	0
575	Sugar Maple	Acer saccharum	25	Р	Р	Р	60	2	Main stem dead, only lower branches alive	Private	Remove	0
576	Sugar Maple	Acer saccharum	20.5	G	G	F-G		2		Private	Remove	1

Tree #	Common Name	Scientific Name	DBH	TI	cs	CV	CDB	DL	Comments	Owner	Action	Comp.
577	Sugar Maple	Acer saccharum	28	P-F	G	F-G		2	Seam (L) with vertical crack	Private	Remove	0
578	Silver Maple	Acer saccharinum	14, 13, 13, 11, <10	F-G	G	G		3	Union at base with 7 stems	Private	Preserve	
579	Willow	Salix spp.	13	G	G	G		2		Private	Preserve	
580	Willow	Salix spp.	18	F-G	G	G		2	Union at 1.8m	Private	Preserve	
581	Willow	Salix spp.	21, 18	F-G	G	G		2	Co-dominance at 1m	Private	Preserve	
582	Willow	Salix spp.	32	G	G	G		3	Epicormic branches (H)	Private	Preserve	
583	Willow	Salix spp.	28	G	G	G		3		Private	Preserve	
584	Willow	Salix spp.	13, 12, 8	G	G	G		3	Union at base	Private	Preserve	
585	Willow	Salix spp.	12, 9	G	G	G		2	Union at 0.5m	Private	Preserve	
586	Crimson King Maple	Acer platanoides 'Crimson King'	18	F	G	F		2	Seam (M), chlorosis (H)	Private	Remove	1
587	Crimson King Maple	Acer platanoides 'Crimson King'	14.5	G	G	F		2	Chlorosis (H)	Private	Remove	1
588	Crimson King Maple	Acer platanoides 'Crimson King'	16	F	G	F		1.5	Seam (M), chlorosis (H)	Private	Remove	1
589	Crimson King Maple	Acer platanoides 'Crimson King'	12	F	G	F		1	Seam (M), chlorosis (H)	Private	Remove	1
590	Crimson King Maple	Acer platanoides 'Crimson King'	11	F-G	G	F		1	Seam (L), chlorosis (H)	Private	Remove	1
591	Crimson King Maple	Acer platanoides 'Crimson King'	21	P-F	G	F		2	Frost crack (H), chlorosis (H)	Private	Remove	0
592	Crimson King Maple	Acer platanoides 'Crimson King'	14.5	G	G	F		1.5	Chlorosis (H)	Private	Remove	1
593	Crimson King Maple	Acer platanoides 'Crimson King'	17	F	G	F		2	Seam (M), spiral stem, chlorosis (H)	Private	Remove	1
594	Crimson King Maple	Acer platanoides 'Crimson King'	14	Р	G	F		1	Frost crack (H) with rot, chlorosis (H), crook (L)	Private	Remove	0
595	Crimson King Maple	Acer platanoides 'Crimson King'	10	G	G	F		1	Chlorosis (H), ts (M)	Private	Remove	1
596	Crimson King Maple	Acer platanoides 'Crimson King'	15	G	G	F		1.5	Chlorosis (H)	Private	Remove	1
597	Crimson King Maple	Acer platanoides 'Crimson King'	15.5	G	G	F		1.5	Chlorosis (H)	Private	Remove	1
598	Crimson King Maple	Acer platanoides 'Crimson King'	15.5	G	G	F		1.5	Chlorosis (H)	Private	Remove	1
599	Crimson King Maple	Acer platanoides 'Crimson King'	13	G	G	F		1	Chlorosis (H)	Private	Remove	1
600	Blue Spruce	Picea pungens	18	G	G	G		1.5		Private	Remove	1

Tree #	Common Name	Scientific Name	DBH	TI	CS	CV	CDB	DL	Comments	Owner	Action	Comp.
А	Apple	Malus spp.	~20-30, (avg. 23)	F	G	F		4	1m fp, union at 1m, epicormic branches (H)	Neighbour	Preserve	
В	Honey Locust (shademaster)	Gleditsia triacanthos 'inermis'	~55	G	G	F-G		4	Coppice growth (M)at base, rot on pruning wound (M)	Neighbour	Preserve	
С	Northern Catalpa	Catala speciosa	~60	F-G	G	G		4	Co-dominance at 3m, sweep (L)	Neighbour	Preserve	
D	Blue Spruce	Picea pungens	35	F-G	G	G		2	Sweep (L)	Neighbour	Preserve	
Е	Blue Spruce	Picea pungens	~35	Р	Р	F		2	Lost leader at 3m	Neighbour	Preserve	
F	Norway Spruce	Picea abies	~35	G	G	G		2		Neighbour	Preserve	
G	Norway Spruce	Picea abies	~35	G	G	G		2		Neighbour	Preserve	
Н	Silver Maple	Acer saccharinum	~75	F	G	F	15	6	Co-dominance at 2m with 7 stems	Neighbour	Preserve	
I	Silver Maple	Acer saccharinum	~20	G	G	G		2	beside fence	Neighbour	Preserve	
P1	see Table 2									Private	Remove	76
P2	Blue Spruce	Picea pungens	6-10 (avg. 8)	G	G	G		1.5	15 trees	Private	Preserve	
	Freeman Maple	Acer x freemanii										
P3	Copper Beech	Fagus sylvatica f.Purpurea	<10	G	G	G		1	4 trees in row along fence	Neighbour	Preserve	
											TOTAL	357

	Codes										
DBH	Diameter at Breast Height	(cm)									
TI	Trunk Integrity	(G, F, P)									
CS Crown Structure (G, F, P)											
CV	Crow n Vigor	(G, F, P)									
CDB	Crow n Dieback	(%)									
DL	Dripline (Diameter)	(m)									
Comp.	Comp. Compensation planting										
P = poor	r , $F = fair$, $G = good$, $\sim = estimates$	ate, (VL) = very light, (L)									

P = poor, F = fair, G = good, ~ = estimate, (VL) = very light, (L) = light, (M) = moderate, (H) = heavy

Table 2. Tally for Tree Polygon P1

Location: 12506-12698 Heart Lake Road, Caledon

Date: 27-Aug-25

Surveyor: KH

Stand Analysis Tally (by Species, Size Class and Quality Class)

P1 100% tally

Tree Size Class >>>>	10-20	cm	21-35	cm	36-50	cm	51-65	cm	>65 (em .	тот	AL
Species	Fair/Good	Poor										
Silver Maple (Acer saccharinum)	0	0	12	2	16	3	1	0	0	0	29	5
Compensation	0	0	24	0	48	0	4	0	0	0	76	0

Description

A row of Silver Maple with buckthorns, majority have co-dominant stems

Appendix A. Photographs of Trees





Image 1. Tree 501

Image 2. Tree 502





Image 3. Tree 503

Image 4. Tree 504






Image 6. Tree 506





Image 7. Tree 507

Image 8. Tree 508






Image 9. Tree 509 Image 10. Tree 511





Image 12. Trees 513 (right) and 514



Image 13. Tree 515

Image 14. Trees 516 (right) and 517





Image 15. Tree 518 (right) and

Image 16. Tree 518 – main stem





Image 17. Tree 519

Image 18. Trees 520 (left) and 521






Image 19. Tree 522 Image 20. Tree 523






Image 21. Tree 524

Image 22. Tree 525





Image 23. Tree 526

Image 24. Trees 527 (left) and 528





Image 25. Tree 529 Image 26. Tree 530






Image 27. Trees 531 (left) and 532

Image 28. Tree 533






Image 29. Tree 534 Image 30. Tree 535





Image 31. Tree 536 Image 32. Tree 537





Image 33. Tree 538 Image 34. Tree 539



Image 35. Trees 540-544 (from left)



Image 36. Tree 542 - base

Image 37. Trees 545 (left) and 546








Image 39. Trees 550 (left) and 551






Image 40. Tree 552

Image 41. Trees 553-557 (from left)



Image 42. Tree 558



Image 43. Trees 559-561 (from left)



Image 44. Trees 562-564 (from left)




Image 45. Trees 565 (left) and 566

Image 46. Trees 569 (right) and 570



Image 47. Trees 567 (left) and 568





Image 48. Trees 571 (left) and 572

Image 49. Tree 573



Image 50. Trees 574 (right) and 575






Image 51. Tree 578

Image 52. Trees 579 (left) and 580

Kuntz Forestry Consulting Inc. P4768 Page 46






Image 53. Trees 581 (left) and 582

Image 54. Tree 583





Image 55. Tree 584

Image 56. Tree 585



Image 57. Tree A



Image 58. Trees B (right) and C



Image 59. Trees D-G (from right)





Image 60. Tree H Image 61. Tree I

Kuntz Forestry Consulting Inc. P4768 Page 52



Image 62. Tree P1 on the north side



Image 63. Tree P1 on the west side



Image 64. Trees 585 (right) and 586





Image 66. Tree 588





Image 68. Tree 590





Image 69. Tree 591

Image 70. Tree 592





Image 71. Tree 594

Image 72. Tree 595





Image 73. Tree 596

Image 74. Tree 597





Image 75. Tree 598

Image 76. Tree 599



Image 77. Trees 600, 351-354 (from right)





Image 78. Tree 355





Image 81. Tree 358



Image 82. Trees 359-361 (from left)



Image 83. Trees 362-364 (from left)



Image 84. Trees 365-367 (from left)



Image 85. Trees 368-370 (from left)



Image 86. Trees 371 (left) and 372



Image 87. Trees 373 (left) and 374



Image 88. Trees 375 (left) and 376






Image 89. Tree 377

Image 90. Tree 378










Image 93. Trees 384 (right) and 385





Image 94. Tree 386

Image 95. Trees 387 (right) and 388

Kuntz Forestry Consulting Inc. P4768 Page 75



Image 96. Trees 389-393 (from right)






Image 97. Tree 394

Image 98. Tree 394 - base



Image 99. Tree 397

Image 100. Tree 397 - cankers



Image 101. Trees 398-400 (from right)




Image 102. Tree 398 - lower stem



Image 103. Tree 400 – canker



Image 104. Trees 401-405 (from right)



Image 105. Trees 406-408 (from right)






Image 106. Tree 409

Image 107. Tree 409 – lower stem





Image 108. Trees 410 (right) and 411

Image 109. Tree 411 – lower stem





Image 110. Tree 412

Image 111. Trees 413-416 (from right)



Image 112. Trees 417-420 (from right)

Image 113. Tree 421






Image 114. Tree 422

Image 115. Trees 423-426 (from right)



Image 116. Trees 427 (right) and 428



Image 117. Trees 429-432 (from right)



Image 118. Trees 433-435 (from right)

Image 119. Tree 436



Image 120. Trees 437-439 (from right)



Image 121. Trees 440-444 (from right)



Image 122. Tree 445



Image 123. Trees 446-448 (from right)



Image 124. Trees 449-451 (from right)



Image 125. Trees 452-454 (from right)





Image 126. Tree 455

Image 127. Tree 456




Image 128. Trees 457 (right) and 458




Image 129. Trees 459 (left) and 460




Image 130. The existing Red Pine Plantation Forest will be preserved with 12m buffer.














TREE PRESERVATION STANDARD NOTES - PART 2 TREE PRESERVATION STANDARD NOTES - PART 1 Caledon. Milnor grading works will be permitted at the edge of the preservation zone as required to correct localized depressions, and blend to existing grades. This work to be undertaken under the direct supervision of an ISA certified arborist. A certified ISA arborist will undertake proper root pruning in accordance with acceptable arboriculture practices when and if roots of retained trees are to be exposed, damaged, or severed by construction work. The exposed roots will be backfilled with appropriate material as soon as possible to prevent desiccation. Root pruning prior to excavation will help prevent necessary damage to tree roots. The use of low pressure hydrovac to expose roots is recommended, at no additional cost. The Town of Caledon must be notified for all work that impacts the TPZ for temporary removal of a section of hoarding to gain access for fine grading or other works. All works are to be supervised by the Town of Caledon. No cables, wire or ropes of any kind shall be wrapped around or installed in trees to be preserved. No contaminants will be dumped or flushed in the TPZ areas or where feeder roots of trees exist (generally beyond the TPZ areas). Irrigate tree protection zones during drought conditions, June to September to reduce drought stress. Inspect the site daily to ensure hoarding is in place and in good condition. Prior to construction, the trees to be preserved shall be protected with a Tree Protection Barrier. The barrier shall consist of 1.2m (4ft) high orange plastic snow fence wired to T-bars (see Town of Caledon Tree Preservation Fencing, STD 606). If applicable, attach a filter cloth 600mm high to the construction side of the hoarding to act as sediment control. Sediment control fencing shall meet or exceed OPSD-219.110, and be installed to the satisfaction of the Town of Caledon. All supports and bracing used to safely secure the barrier should be located outside the Tree Protection Zone (TPZ). All supports and bracing should minimize damage to roots. The TPZ fence is to be installed along the edge of the tree protection zones. This hoarding is to remain in place and remain in good condition throughout the entire duration of the project. Dismantling the tree protection barrier prior to approval by the Town of Caledon staff may constitute a contravention. The applicant shall notify the Town of Caledon and the consulting certified arborist or landscape architect to confirm that the tree protection barriers are in place. SPECIFICATIONS contin SPECIFICATIONS **During Construction Phase** The following Tree Preservation and Protection Measures will be undertaken to help eliminate and/or significantly reduce construction injury to all trees recommended for preservation. All temporary tree protection measures cited for retained trees must comply with the Town of Caledon Tree Protection Specifications and Details. Any variation from the standard tree protection measures must be approved in writing by the Town of Caledon. All areas within the TPZ shall remain undisturbed for the duration of construction. There will be no grade changes, dumping, and storage of any materials, structures or equipment within these areas. The Tree Protection 3 arrier must not be removed without the written authorization of the Town of colors. General Pre-Construction Phase TOWN OF CALEDON TOWN OF CALEDON NO REVISION Ö N 1 10. 9. Where fill or excavated material must be temporarily located near a TPZ, a wooden barrier must be used to ensure no material enters the TPZ. Remove any garbage and foreign debris from the tree protection zones, daily. For the trees that were recommended for removal and/or crown pruning that are within the TPZ limits, these activities are to be performed by a qualified ISA certified arborist prior to the installation of the Tree Protection Zone barriers and prior to the commencement of any construction activities. Install the Tree Protection Zone barrier as per Tree Preservation Fencing, STD 606 at the limits shown on the tree inventory and protection plan after the tree removal, whichever is greater, and crown pruning activities are completed. A Tree Protection Zone sign must be mounted on all sides of the tree protection barrier for the duration of site construction. The sign should be a minimum of 40cm x 60cm and made of white gator board or equivalent material. The sign must be similar to the illustration shown below, or as directed by the Town of Caledon. Following the completion of all site works including landscaping, and after review and approval by the Town of Caledon staff, the protective hoarding may be removed. After removal of the protective hoarding, the Tree Preservation Zones shall inspected by the Town of Caledon staff. Any remaining dead, diseased, or hazardous limbs or trees are to be removed by an ISA certified arborist as directed by the consulting arborist or Town of Caledon staff. All contractors and site visitors should be informed of the tree preservation and protection measures at a pre-construction meetin The tree protection barrier must not be authorization of the Town of Caledon. Post Construction Phase TREE PROTECTION ZONE k is permitted in the Tree Protectio APR'D DATE STANDARD No. 710 B.B. B.M. DATE: AUGUST 17 AUGUST 17 SIN STN


NO

REVISION

APR'D

DATE

STANDARD No. 711



LEGEND

NO.	Issue/Revisions		Date	Бу
_	Report Submission		14 Oct. '25	줏
Base D	Base Data: J. D. Barnes Ltd. (topo)			
	FORESTRY CONSULTING Inc.	PO Box 1267 Lakeshore W PO 146 Lakeshore Road West Oakville ON L6K 0B3 289.837.1871 www.kuntzforestry.ca consult@kuntzforestry.ca	0x 1267 Lakeshore W PO 46 Lakeshore Road West Oakville ON L6K 0B3 289.837.1871 www.kuntzforestry.ca consult@kuntzforestry.ca	n n → ω # O

byPATH: Landscape Architecture Inc.

Tree Inventory & Preservation Plan 12506 and 12698 Heart Lake Road Caledon

Project Scale P4768 1:350 14 October 2025