DADTNEDS

ASSOCIATES

BRYN BARRON, OALA, CSLA, ISA ALISTAIR JOHNSTON, LOHTA, ISA, ASCA MATHIEU STRYBOS, OALA, CSLA SALVATORE VIOLA, OALA, CSLA MATTHEW REGIMBAL, LOHTA, ISA JOSHUA BEITZ, OALA, CSLA, ISA

# **ARBORIST REPORT**

## PROPOSED 30 UNIT TOWNHOUSE DEVELOPMENT 18314 & 18309 HURONTARIO STREET TOWN OF CALEDON, ONTARIO

PREPARED FOR: MILANI GROUP P.O. BOX 663 MAPLE, ONTARIO L6P 1A1

PREPARED BY:
STRYBOS BARRON KING LTD.
5770 HURONTARIO STREET
SUITE 320
MISSISSAUGA, ONTARIO
L5R 3G5

ISA CERTIFIED ARBORIST MATTHEW GEHRES ON-1114A OUR PROJECT NO: 19, 5402

**December 11, 2020** 

# **TABLE OF CONTENTS**

Introduction	1
Site Context	1
Plans Utilized	1
Tree InventoryInventory ListInventory Summary	2
Recommendations	3
Town Requirements	3
Tree Protection Measures Pre-Construction During Construction	3
Conclusion	4
Appendix A – Key Map	5
Appendix B – Tree Inventory and Preservation Plan (Context Plan)	6
Appendix C – Site Photos	7
Appendix D –Tree Protection Hoarding Detail	9
Enclosed: Tree Inventory & Preservation Plan	

18314 & 18309 Hurontario Street – Town of Caledon December 11, 2020

### Introduction

Strybos Barron King Ltd. was retained by Milani Group to prepare an Arborist Report for the subject property in accordance with Town of Caledon requirements. The purpose of this study is to determine the composition, character and health of existing trees and assess opportunities for preservation in relation to a proposed Townhouse Development. The subject property is located at 18314 & 18309 Hurontario Street in the Town of Caledon, Ontario.

(See Appendix A - Key Map).

## **Site Context**

The subject site is located on the west side of Hurontario Street, on the south side of Caledon Village. Currently, the site is vacant with the exception of the existing dwelling at the northeast corner of the site. The property abuts single family dwellings to the north, a vacant field to the west and single family lots to the south. The site fronts on to Hurontario Street.

## **Plans Utilized**

A conceptual Site Plan prepared by RN Design as well as aerial imagery of the site was used to determine the location of trees in relation to the proposed future development works.

#### Tree Inventory

Trees were identified within and immediately adjacent to the subject property. The trees are described in terms of species and diameter at breast height (DBH – measured at 1.4m from grade). They have been assessed in terms of their general health from poor to good; **GOOD** – trees in good overall health and condition with desirable structure, **FAIR** – trees in moderate health and condition with less desirable structure, and **POOR** – trees displaying prominent health issues such as decay and disease and/or poor form and structure.

Jan 06, 2021

# STRYBOS BARRON KING LTD.

Arborist Report 18314 & 18309 Hurontario Street – Town of Caledon December 11, 2020

Page 2

		Diameter	Crown	Health				Minimum	
Tag No.	Tree Species	(cm)	Dia. (m)	G/F/P	Structure	Comments	Action	TPZ	Tag No.
60	WALNUT	41	17	GOOD	GOOD	CROWDED BY ADJACENT TREES. MINOR DEADWOOD.	PRESERVE	3	60
61	MANITOBA MAPLE	63	13	FAIR	POOR	SLIGHT LIEAN. LARGE HANGER IN CANOPY. MAJOR DEADWOOD. NATURALIZED. CROWDED BY ADJACENT TREES.	PRESERVE	4.2	61
62	WALNUT	30	8		FAIR	HIGH CROWN. MINOR DEADWOOD. CROWDED BY ADJACENT TREES.	REMOVE	NA	62
63	WALNUT	35	8	GOOD		HIGH CROWN. MINOR DEADWOOD. CROWDED BY ADJACENT TREES.	REMOVE	NA	63
64	MANITOBA MAPLE	28	6	POOR		MAIN STEMS FAILED. HEAVY LEAN. MAJOR DEADWOOD. CROWDED BY ADJACENT TREES.	REMOVE	NA	64
65	WALNUT	32	5		FAIR	HIGH CROWN. THIN CROWN. MINOR DEADWOOD. CROWDED BY ADJACENT TREES.	REMOVE	NA	65
66	MANITOBA MAPLE	29	6		FAIR	NATURALIZED. STEM FAILURE AT BASE. MAJOR DEADWOOD. CROWDED BY ADJACENT TREES.	REMOVE	NA	66
67	MANITOBA MAPLE	20	3		POOR	DAMAGED TOP. CROWDED BY ADJACENT TREES. NATURALIZED. MAJOR DEADWOOD.	REMOVE	NA	67
68	MANITOBA MAPLE	22	3		POOR	FAILED. MAJOR DEADWOOD. NATURALIZED.	REMOVE	NA	68
69	WALNUT	33	6		GOOD	HIGH CROWN. MINOR DEADWOOD. CROWDED BY ADJACENT TREES.	REMOVE	NA	69
70	MANITOBA MAPLE	75	9		POOR	FAILED. MAJOR DEADWOOD. NATURALIZED. LARGE SUCKER GROWTH AT BASE.	REMOVE	NA	70
71	MANITOBA MAPLE	54	8		POOR	FAILED. MAJOR DEADWOOD. NATURALIZED. LARGE SUCKER GROWTH AT BASE.	REMOVE	NA	71
72	WALNUT	24	6		FAIR	HIGH CROWN. CROWDED BY ADJACENT TREES. COVERED IN VINES. MINOR DEADWOOD.	REMOVE	NA	72
73	BASSWOOD	59	6	FAIR	FAIR	CROWDED BY ADJACENT TREES. MINOR DEADWOOD.	REMOVE	NA	73
74	MANITOBA MAPLE	28	4		FAIR	CROWDED BY ADJACENT TREES. MINOR DEADWOOD. NATURALIZED.	REMOVE	NA	74
75	BASSWOOD	27	5		FAIR	CROWDED BY ADJACENT TREES. MINOR DEADWOOD.	REMOVE	NA	75
76	MANITOBA MAPLE	24	4		POOR	CROWDED BY ADJACENT TREES. MINOR DEADWOOD. NATURALIZED.	REMOVE	NA	76
77	BASSWOOD	10/20/20	9		FAIR	CROWDED BY ADJACENT TREES. MINOR DEADWOOD. CO-DOMINANT STEMS.	REMOVE	NA NA	77
78	MANITOBA MAPLE	19/20	5	POOR		SLIGHT LEAN. MINOR DEADWOOD. CROWDED BY ADJACENT TREES. NATURALIZED.	REMOVE	NA	78
79	MANITOBA MAPLE	18/18/21/21	6	POOR	POOR	CO-DOMINANT STEMS. MINOR DEADWOOD. CROWDED BY ADJACENT TREES. NATURALIZED.	REMOVE	NA	79
80	WALNUT	37	5		FAIR	CROWDED BY ADJACENT TREES. MINOR DEADWOOD.	REMOVE	NA	80
81	WALNUT	21	8	FAIR	FAIR	CROWDED BY ADJACENT TREES. MINOR DEADWOOD.	REMOVE	NA	81
82	NORWAY MAPLE CRIMSON KING	30	6	GOOD	GOOD	MINOR DEADWOOD. THIN CANOPY	REMOVE	NA	82
83	WALNUT	30	13	GOOD	GOOD	NATURALIZED. MINOR DEADWOOD.	REMOVE	NA	83
84	NORWAY MAPLE	34	8	FAIR	FAIR	MAJOR DEADWOOD. WOUND ON MAIN TRUNK. MINOR DEADWOOD.	REMOVE	NA	84
85	SILVER MAPLE	54	6	FAIR	FAIR	MINOR DEADWOOD. CROWDED BY ADJACENT TREES.	REMOVE	NA	85
86	WALNUT	28	6	FAIR	FAIR	MINOR DEADWOOD. CANOPY TO THE GROUND. CROWDED BY ADJACENT TREE.	REMOVE	NA	86
87	SILVER MAPLE	20	6	FAIR	FAIR	MINOR DEADWOOD. THIN CROWN. CROWDED BY ADJACENT TREE.	REMOVE	NA	87
88	WALNUT	24	6	GOOD	GOOD	MINOR DEADWOOD. CANOPY TO THE GROUND. CROWDED BY ADJACENT TREE.	REMOVE	NA	88
89	MANITOBA MAPLE	67	16	FAIR	FAIR	NATURALIZED. MINOR DEADWOOD.	REMOVE	NA	89
90	BIRCH	16/37	8	FAIR	FAIR	MINOR DEADWOOD. THIN CROWN. CROWDED BY ADJACENT TREE.	REMOVE	NA	90
91	BLACK LOCUST	86	10	GOOD	FAIR	CO-DOMINANT STEMS. MINOR DEADWOOD. CROWDED BY ADJACENT TREES. NATURALIZED.	REMOVE	NA	91
92	POPLAR	75	14	FAIR	POOR	HEAVY LEAN. CROWDED BY ADJACENT TREES, MAJOR DEADWOOD.	REMOVE	NA	92
93	SIBERIAN ELM	17	5	FAIR	FAIR	CROWDED BY ADJACENT TREE. MINOR DEADWOOD. NATURALIZED.	REMOVE	NA	93
94	BLACK LOCUST	20/33	5		FAIR	MINOR DEADWOOD. CROWDED BY ADJACENT TREES.	REMOVE	NA	94
95	NORWAY MAPLE	20	5	FAIR	FAIR	MINOR DEADWOOD.	REMOVE	NA	95
96	COLORADO SPRUCE	20	4		FAIR	MINOR INNER DEADWOOD. CROWDED BY ADJACENT TREES.	REMOVE	NA	96
97	MANITOBA MAPLE	24/27	3		POOR	HEAVY LEAN. CROWDED BY ADJACENT TREES, MAJOR DEADWOOD. BROKEN TOP.	REMOVE	NA	97
98	BLACK LOCUST	57	9		FAIR	CROWDED BY ADJACENT TREES. MINOR DEADWOOD. HIGH CROWN.	REMOVE	NA	98
99	COLORADO SPRUCE	24	6		GOOD	MINOR INNER DEADWOOD. CROWDED BY ADJACENT TREES.	REMOVE	NA	99
100	COLORADO SPRUCE	20	6		GOOD	MINOR INNER DEADWOOD. CROWDED BY ADJACENT TREES.	REMOVE	NA	100
101	COLORADO SPRUCE	37	6		GOOD	MINOR INNER DEADWOOD. CROWDED BY ADJACENT TREES.	REMOVE	NA	101
102	COLORADO SPRUCE	28	6		GOOD	MINOR INNER DEADWOOD. CROWDED BY ADJACENT TREES.	REMOVE	NA	102
103	COLORADO SPRUCE	30	6	GOOD		MINOR INNER DEADWOOD. CROWDED BY ADJACENT TREES.	REMOVE	NA	103
104	AUSTRIAN PINE	39	7		GOOD	MINOR INNER DEADWOOD. CROWDED BY ADJACENT TREES.	REMOVE	NA	104
105	AUSTRIAN PINE	35	7	GOOD		MINOR INNER DEADWOOD. CROWDED BY ADJACENT TREES.	REMOVE	NA	105
106	AUSTRIAN PINE	39	7		GOOD	MINOR INNER DEADWOOD. CROWDED BY ADJACENT TREES.	REMOVE	NA	106
107	MANITOBA MAPLE	26/26/26	6	FAIR	FAIR	CO-DOMINANT STEMS. MINOR DEADWOOD. CROWDED BY ADJACENT TREES. NATURALIZED.	REMOVE	NA	107
108	BASSWOOD	12/18/24/32		FAIR	POOR	CO-DOMINANT STEMS. MINOR DEADWOOD. CROWDED BY ADJACENT TREES. NATURALIZED.	REMOVE	NA	108
	BASSWOOD	36/36	12	FAIR		CO-DOMINANT STEMS. MINOR DEADWOOD. CROWDED BY ADJACENT TREES. NATURALIZED.	REMOVE	NA	109
	MULLBERRY	76	11	POOR		MINOR DEADWOOD THROUGHOUT CANOPY. WOUND ON TRUNK. TREE IN DECLINE. THIN CROWN.	REMOVE	NA	110
	COLORADO SPRUCE	23	6	GOOD		MINOR INNER DEADWOOD. CROWDED BY ADJACENT TREES.	REMOVE	NA	111
	COLORADO SPRUCE	22	5	GOOD		MINOR INNER DEADWOOD. CROWDED BY ADJACENT TREES.	REMOVE	NA	112
113	CEDAR	38	3	POOR		HIGH CROWN. POORLY PRUNED. TREE IN DECLINE. MINOR DEADWOOD.	REMOVE	NA	113
114	CEDAR	42	6	FAIR	FAIR	MINOR INNER DEADWOOD. CROWDED BY ADJACENT TREES.	PRESERVE	3	114
115	CEDAR HEADGE ROW (20 STEMS)	20-35	5	FAIR	FAIR	TIGHTLY PACKED CEDARS. MINOR INNER DEADWOOD. CROWDED TOGETHER. SOME ARE LEANING.	PRESERVE	2.4	115
116	HORSECHESTNUT	42/95	9	FAIR	FAIR	CO-DOMINANT STEMS. MINOR DEADWOOD. CROWDED BY ADJACENT TREES.	PRESERVE	6	116
117	HEDGE ROW (MIXED CONIFERS)	20-42	6	GOOD	GOOD	MIX OF SPRUCE AND PINE. TIGHTLY PLANTED TOGETHER TO FORM A HEDGE. MINOR INNER DEADWOOD. CROWED BY NEIGHBORING TREES.	PRESERVE	3	117
118	SCOT PINE	32	6	GOOD	GOOD	MINOR DEADWOOD.	REMOVE	NA	118
			. <u> </u>		,	<u> </u>			

18314 & 18309 Hurontario Street – Town of Caledon December 11, 2020

Refer to attached Appendix B and attached plan V100 - *Tree Inventory and Preservation Plan* for locations of, and details pertaining to specific trees.

#### **Inventory Summary**

The subject site is currently vacant with the exception of the existing dwelling at the northeast corner of the property. The internal portion of the site is sparsely treed and is limited to remnant Colorado Spruce and Austrian Pine hedgerows as well as naturalized groupings and individual trees composed mainly of Norway Maple, Silver Maple, Black Walnut, Black Locust and Manitoba Maple trees. A naturalized grouping primarily composed of Black Walnut, Manitoba Maple and Basswood trees occurs along the north property limit. Cedar hedgerows compose most of the south property limit as well as groupings of Colorado Spruce trees

#### Recommendations

Based on the conceptual Site Plan, all of the trees internal to the property will require removal. The naturalized groupings of trees, beyond the north limit of the site will also require removal to accommodate the future Brock Street extension. With the exception of some of the individual trees at the southeast corner of the site, and pending detailed site grading limits along the south limit, the coniferous hedgerows along the south property limit can be preserved.

# **Town Requirements**

- Any trees located on the property line or on the adjacent property that are
  proposed to be removed or pruned, will require written consent from the adjacent
  landowner. All correspondence is to be forwarded to the Town prior to any
  removals.
- 2:1 tree compensation will be required for all tree removals. Tree compensation
  planting is in addition to the standard required planting. In the event that tree
  compensation cannot be accommodated for in the planting design, financial
  compensation shall be collected at a rate (per tree) as determined by the Town.
  Based on the replacement ratio, 28 replacement trees are required for the
  removal of the trees on the subject property.

#### **Tree Protection Measures** (Refer to Appendix D)

The following tree protection measures should be undertaken by the owner.

#### **Pre-Construction**

- Prior to construction, tree protection hoarding is to be installed at the limits shown on the V100. The hoarding shall be maintained for the duration of site construction. It shall not be removed until authorized by the Consulting Arborist.
- The limits of protection hoarding shall be confirmed in the field by the Consulting Arborist and the Town of Caledon.
- Tree removals should occur outside of the breeding bird season. If this is not possible, clearance with an ecologist should occur prior to construction to ensure no loss of bird nest, egg or unfledged young.

18314 & 18309 Hurontario Street – Town of Caledon December 11, 2020

### **During Construction**

- Areas within the protection hoarding shall remain undisturbed for the duration of site construction and shall not be used for the storage of excavated fill, building materials, structures or equipment.
- Minor grading works will be permitted at the edge of the preservation zone as required to correct localized depressions adjacent to the new development. This work to be undertaken under the supervision of the Consulting Arborist.
- During construction and prior to Assumption of the Subdivision by the Town, the
  consulting Arborist along with appropriate Town staff shall inspect the entire site.
  Any noted hazardous trees must be identified and removed prior to Assumption.
  Any records of maintenance or removals are to be submitted to the Town of
  Caledon.

#### Conclusion

Strybos Barron King Ltd. was retained by Milani Group to prepare an Arborist Report for the subject property in accordance with Town of Caledon requirements.

The property is mainly composed of remnant, naturalized groupings of trees and hedgerows. As part of the site planning, the existing dwelling at the northeast limit of the property is to remain. A new, future road will be constructed north of the site to provide access to the development. Existing, coniferous hedgerows flank the south property limit.

Based on the proposed conceptual Site Plan and pending detailed rear lot grading requirements, the hedgerows along the south property limit are recommended for preservation. All other trees, internal to the property, are to be removed to accommodate the proposed development.

**Prepared By:** 

STRYBOS BARRON KING LTD.

Matthew Gehres

ISA Certified Arborist ISA ON-1114A Senior Landscape Technologist Jan 06 STRYBOS BARRON KING LTD. Page 5

Arborist Report 18314 & 18309 Hurontario Street – Town of Caledon December 11, 2020


# Appendix A -KEY MAP



18314 & 18309 Hurontario Street – Town of Caledon December 11, 2020

# Appendix B - TREE INVENTORY AND PRESERVATION PLAN (Context Plan)

THE KING'S HIGHWAY No. 10



Page 7


# Appendix C – SITE PHOTOS



Page 8

18314 & 18309 Hurontario Street – Town of Caledon December 11, 2020







Southwest property limit – view south

Jan 06, 2021

Arborist Report

18314 & 18309 Hurontario Street – Town of Caledon December 11, 2020

## Appendix D - TREE PROTECTION HOARDING DETAIL

