



LEGEND

- Property Boundary
- # Approx. Borehole Locations
(Geotechnical Investigation
Shaneen & Peaker Ltd., 2006)
- PSI - Poorly Sorted Outwash
Sandy Loam
Ref: Soil Map of Peel County
Soil Survey Report No. 18
- Drainage Direction

40m 0 80m
HORIZONTAL SCALE 1:1,500



Soil Drainage and Classification
Van Stralen EIS

Lot 28, Concession 9
Town of Caledon, ON

Date Issued:	January 2020	Figure No. 5
Created By:	JLM	
Project No.	06-057	
Reference:	First Base Solutions	